BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Providing and laying HDPE water line in Channappa Garden and Sundarnagar Block 2 in JP Park ward 17
2	Administration Approval & Date	JC/RRN/AS/2248/2013-14 Dtd: 17.09.2013
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/295/2013-14 Dtd: 18.09.2013
4	Estimate Amount	49,90,000/-
5	Job Code No.	017-14-000016
6	P-Code	P-2201
7	Agreement No and Date:	EE/RRND/Agmt/220/13-14 Dtd: 05.02.2014
8	Work order Number & Date	EE/RRND/WO/220/13-14 Dtd: 05.02.2014
9	Contract Amount as per Agreement	Rs. 53,35,679/-
10	Bill Amount	Rs. 48,69,637=91
11	B.R No. & Date	320/14-15 Dtd: 31.07.2014
12	Agency	L Nithyananda Prabhu
13	M.B. Number & Page No. of Measurement records	85/12-13 Page No 8472 to 8479
14	Date of Inspection	07.09.2017
15	Enclosures	2 Number of photos taken during inspection
16	I have Inspected the above Location along with the Conserned person, as per EE (RRND) Letter No EE/RRN/PR/414/A/17-18 Dated 1-9-2017. It is observed that the Items indicated in the Xerox Copy of MB/XL sheets are not susceptible for measurements and also Inspection Report the asphalting of Roads has been made after Completion of above work, as such the photos taken during the execution of work has been scrutinised and Inspected, it appears that the above work has been done. This has a reference to the NOC Issued by Lokayukta vide Letter No LOK/INV(J) CT/Crime 60/2014 Dated 1-8-2017	

EE (RRN) Division, RR Nagara Zone.

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ರಾಜರಾಜೇಶ್ವರಿನಗರ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು - 98

7/9/2017
(R. Sathyanarayana)
Inspection Report Officer.

R. SATHYANARAYANA
INSPECTION OFFICER

Scanned by CamScanner